

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Engine Controls and Fuel - 6.2L \(LT2\)](#)
- 3. [Repair Instructions](#)
- 4.

Mass Airflow Sensor Replacement (Convertible)

[Click here for full size](#)
[Radiator Surge Tank Replacement](#)

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Mass Airflow Sensor Bolt [2x] Caution: Refer to
2	Mass Airflow Sensor Procedure Disconnect the electrical connector.