


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Throttle Body Assembly Replacement



[Click here for full size](#)
Air Cleaner Outlet Duct Replacement

•

Air Cleaner Assembly Replacement

Fastener Caution.

Tighten

10N-m (89 lb in)

Throttle Body Idle Air Flow Compensation Reset

Callout	Component Name
Preliminary Procedures	
1.	
1	Throttle Body Bolt [4>x]
	Caution:
	Refer to

Callout	Component Name
2	Throttle Body Procedure 1. Disconnect the electrical connectors. 2. Install NEW throttle body gasket/seals. 3. Perform the throttle body idle air flow compensation reset.

mcx30.com