

2022 CHEVROLET CORVETTE SERVICE MANUAL


- SEARCH

1. [Engine/Propulsion](#)
2. [Engine Heating and Cooling](#)
3. [Repair Instructions](#)
- 4.


Auxiliary Engine Coolant Fan Replacement - Left Side (with V09)

Removal Procedure

1. Rear Wheelhouse Liner >> Reposition - Rear Wheelhouse Liner Replacement - Left Side



2.
[Click here for full size](#)
3. Disconnect the electrical connector (2) from the auxiliary engine cooler fan electrical connector (1).



4.
[Click here for full size](#)