

2022 CHEVROLET CORVETTE SERVICE MANUAL


- SEARCH

1. [Engine/Propulsion](#)
2. [Engine Heating and Cooling](#)
3. [Repair Instructions](#)
- 4.


Auxiliary Engine Coolant Fan Replacement - Left Side (with V09)

Removal Procedure

1. Rear Wheelhouse Liner >> Reposition - Rear Wheelhouse Liner Replacement - Left Side




2.
[Click here for full size](#)
3. Disconnect the electrical connector (2) from the auxiliary engine cooler fan electrical connector (1).



4.
[Click here for full size](#)


5. Engine Coolant Fan Shroud Bolt (1) >> Remove




6.
[Click here for full size](#)

7. Auxiliary Engine Coolant Fan (1) >> Remove


Installation Procedure



1.
[Click here for full size](#)
2. Auxiliary Engine Coolant Fan (1) >> Install



3. [Click here for full size](#)
4. **Caution:**
Refer to Fastener Caution
5. Engine Coolant Fan Shroud Bolt (1) >> Install and tighten 7 N-m (62 lb in)



6. [Click here for full size](#)
7. Connect the electrical connector (2) to the auxiliary engine cooler fan electrical connector (1).
8. Rear Wheelhouse Liner >> Install - Rear Wheelhouse Liner Replacement - Left Side