


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Mechanical - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Intake Manifold Cover Replacement



Click here for full size
Fastener Caution.

Tighten

9 N-m (80 lb in)

Callout	Component Name
1	Intake Manifold Cover Bolt [4x] Caution: Refer to
2	Evaporative Emission Canister Vent Pipe Clip Procedure Disconnect clip holding the evaporative emission canister purge pipe.
3	Intake Manifold Cover Procedure Pull the intake manifold cover upward to remove.