


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Mechanical - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Valve Lifter Follower Guide Replacement



[Click here for full size](#)
Engine Block Valley Cover Replacement

Fastener Caution.

Tighten

12 N-m (106 lb in)

Callout	Component Name
Preliminary Procedure	
1	Valve Lifter Follower Guide Bolt
	Caution:
	Refer to
2	Valve Lifter Follower Guide
3	Valve Lifter Follower