

SECTION 206-06: Hydraulic Brake Actuation
DIAGNOSIS AND TESTING

2014 F-150 Workshop Manual
Procedure revision date: 10/25/2013

Diagnostic Trouble Code (DTC) Charts

Steering Column Control Module (SCCM) DTC Chart

DTC	Description	Action
B1368:11	Adjustable Pedal Position Feedback Sensor: Circuit Short To Ground	GO to Pinpoint Test C .
B1368:12	Adjustable Pedal Position Feedback Sensor: Circuit Short To Battery	GO to Pinpoint Test C .
B1369:09	Pedal Adjustment Switch: Component Failure	INSTALL a new brake pedal control switch. REFER to Brake Pedal Control Switch in this section. CLEAR the DTCs. REPEAT the self-test. If DTC B1369:09 returns, INSTALL a new Steering Column Control Module (SCCM). REFER to Section 211-05 . CLEAR the DTCs. REPEAT the self-test. TEST the system for normal operation.
B137D:18	Pedal Adjustment Motor: Circuit Current Below Threshold	GO to Pinpoint Test A .
B137D:19	Pedal Adjustment Motor: Circuit Current Above Threshold	GO to Pinpoint Test A .
B137D:71	Pedal Adjustment Motor: Actuator Stuck	GO to Pinpoint Test A .
B1D36:09	Turn Indicator Switch: Component Failure	REFER to Section 417-01 .
All other SCCM DTCs	—	REFER to Section 211-05 .

mcx30.com