


SECTION 303-00: Engine System — General Information
GENERAL PROCEDURES

2014 F-150 Workshop Manual
Procedure revision date: 10/25/2013


Valve Tappet Inspection

OHC engines

1. Inspect the valve tappet for damage, especially in the indicated areas. If any damage is evident, inspect the camshaft lobes and valves for damage. Replace components as necessary.



Push rod engines



mcx30.com