

No	The system is operating correctly at this time. The concern may have been caused by module connections. ADDRESS the root cause of any connector or pin issues.
----	--

DIAGNOSIS AND TESTING > BODY CONTROL MODULE (BCM) > PINPOINT TESTS > PINPOINT TEST D : U0151:87

Normal Operation and Fault Conditions

The BCM communicates with the RCM through the GWM. REFER to: Communications Network - System Operation and Component Description .

DTC Fault Trigger Conditions

DTC	Description	Fault Trigger Conditions
U0151:87	Lost Communication With Restraints Control Module: Missing Message	A continuous memory DTC that sets in the BCM if SRS messages received from the RCM through the GWM are missing.

Possible Sources

- Communication network concern
- Battery voltage concern
- RCM
- BCM

DIAGNOSIS AND TESTING > BODY CONTROL MODULE (BCM) > PINPOINT TESTS > PINPOINT TEST D : U0151:87 > PINPOINT TEST D : U0151:87



NOTE: If new modules were installed prior to the DTC being set, the module configuration may be incorrectly set during the PMI or the PMI may not have been carried out.

D1 VERIFY THE CUSTOMER CONCERN

Ignition ON.

Verify there is an observable symptom present.

Is an observable symptom present?

Yes	GO to D2
-----	----------

No	The system is operating normally at this time. The DTC may have been set due to high
----	--