


	TKIT-2008ET-ROW
	303-300 (T87C-6565-A) Set, Valve Spring Compressor T88C-1000-ST TKIT-1988-FESTIVA TKIT-1988-TRACER TKIT-2009TC-F
	303-350 (T89P-6565-A) Compressor, Valve Spring TKIT-1989-F TKIT-1989-FLM TKIT-1989-FM TKIT-1990-LMH

Materials

Name	Specification
Motorcraft® SAE 5W-20 Premium Synthetic Blend Motor Oil (U.S.) XO-5W20-QSP (U.S.)	WSS-M2C945-A
Motorcraft® Orange Antifreeze/Coolant Concentrated (U.S.) VC-3-B (U.S.)	WSS-M97B44-D

DISASSEMBLY AND ASSEMBLY OF SUBASSEMBLIES > CYLINDER HEAD > DISASSEMBLY



NOTE: During engine repair procedures, cleanliness is extremely important. Any foreign material, including any material created while cleaning gasket surfaces, that enters the oil passages, coolant passages or the oil pan, can cause engine failure.