

Possible Causes:

- Restricted fuel filter
- Restricted fuel supply line
- Damaged or worn fuel pump
- Fuel sloshing at low fuel level
- Sudden acceleration
- Vehicle driven on hilly or steep inclines

Diagnostic Aids:

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test HC .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P00BB - FUEL INJECTOR INSUFFICIENT FLOW - FORCED LIMITED POWER - DTC CHART**P00BB - FUEL INJECTOR INSUFFICIENT FLOW - FORCED LIMITED POWER - DTC CHART**

Description: This DTC sets when the requested fuel delivery volume is greater than the fuel injectors maximum delivery volume.

Possible Causes:

- High ethanol content in the fuel tank
- Customer driving habits
- Restricted fuel filter
- Restricted fuel supply line
- Damaged or worn fuel pump

Diagnostic Aids: A high fuel ethanol content combined with pulling or carrying a heavy load up a steep grade could set this DTC.

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test HC .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P00C1 - TURBOCHARGER/SUPERCHARGER BYPASS VALVE B CONTROL CIRCUIT LOW - DTC CHART