

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P0108 - MANIFOLD ABSOLUTE PRESSURE (MAP)/BAROMETRIC PRESSURE (BARO) SENSOR HIGH - DTC CHART

P0108 - MANIFOLD ABSOLUTE PRESSURE (MAP)/BAROMETRIC PRESSURE (BARO) SENSOR HIGH - DTC CHART

Description: This DTC sets when the manifold absolute pressure (MAP) sensor operating voltage is greater than the maximum allowable calibrated parameter of 4.96 volts.

Possible Causes:

- VREF circuit short to voltage
- MAP circuit open
- MAP circuit short to voltage

Diagnostic Aids:

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test DM .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P0109 - MANIFOLD ABSOLUTE PRESSURE (MAP)/BAROMETRIC PRESSURE (BARO) SENSOR INTERMITTENT - DTC CHART

P0109 - MANIFOLD ABSOLUTE PRESSURE (MAP)/BAROMETRIC PRESSURE (BARO) SENSOR INTERMITTENT - DTC CHART

Description: This DTC sets when the manifold absolute pressure (MAP) sensor signal is intermittent.

Possible Causes:

- MAP circuit intermittent open
- MAP circuit intermittent short to voltage
- MAP circuit intermittent short to ground
- Damaged MAP sensor
- Incorrect harness connections

Diagnostic Aids: Check the harness and connection.

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test DM .		