

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P2270 - O2 SENSOR SIGNAL STUCK LEAN - BANK 1, SENSOR 2 - DTC CHART

P2270 - O2 SENSOR SIGNAL STUCK LEAN - BANK 1, SENSOR 2 - DTC CHART

Description: The heated oxygen sensor bank 1, sensor 2 (HO2S12) is forced rich and lean and monitored by the PCM. This DTC sets when the PCM does not detect the output of the HO2S12 in a calibrated amount of time.

Possible Causes:

- Pinched, shorted, and corroded wiring and pins
- Crossed HO2S12 wires
- Exhaust leaks
- Contaminated HO2S12
- Damaged HO2S12

Diagnostic Aids:

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test H .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P2271 - O2 SENSOR SIGNAL STUCK RICH - BANK 1, SENSOR 2 - DTC CHART

P2271 - O2 SENSOR SIGNAL STUCK RICH - BANK 1, SENSOR 2 - DTC CHART

Description: The heated oxygen sensor bank 1, sensor 2 (HO2S12) is forced rich and lean and monitored by the PCM. This DTC sets when the PCM does not detect the output of the HO2S in a calibrated amount of time.

Possible Causes:

- Pinched, shorted, and corroded wiring and pins
- Crossed HO2S12 wires
- Exhaust leaks
- Contaminated HO2S12
- Damaged HO2S12

Diagnostic Aids:

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
-------------	-------------------	-----------------------	-------------------