

- COP2 circuit short to voltage (COP)
- CDB circuit short to voltage (coil pack)
- Damaged COP (if equipped)
- Damaged coil pack (if equipped)
- Damaged ignition coil wiring harness

Diagnostic Aids:

Application	Key On Engine Off	Key On Engine Running	Continuous Memory
Fiesta 1.6L TiVCT	GO to Pinpoint Test JE .		
All others	GO to Pinpoint Test JF .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P2306 - IGNITION COIL C PRIMARY CONTROL CIRCUIT LOW - DTC CHART

P2306 - IGNITION COIL C PRIMARY CONTROL CIRCUIT LOW - DTC CHART

Description: This DTC sets when there is a short to ground in the COP3 circuit.			
Possible Causes:			
• COP3 circuit short to ground • Damaged ignition coil • Damaged ignition coil wiring harness			
Diagnostic Aids:			
Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	GO to Pinpoint Test JF .		

DIAGNOSTIC TROUBLE CODE (DTC) CHARTS AND DESCRIPTIONS > P2307 - IGNITION COIL C PRIMARY CONTROL CIRCUIT HIGH - DTC CHART

P2307 - IGNITION COIL C PRIMARY CONTROL CIRCUIT HIGH - DTC CHART

Description: This DTC sets when there is a short to voltage in the COP3 circuit.			
Possible Causes:			
• COP3 circuit short to voltage			