

(5.0L) > PINPOINT TEST D : RADIO INTERFERENCE

Refer to Charging System for schematic and connector information.

Normal Operation and Fault Conditions

The generator radio suppression equipment reduces interference transmitted through the speakers by the vehicle electrical system.



NOTE: If the Original Equipment Manufacturer (OEM) Audio Control Module (ACM) has been replaced with an aftermarket unit, the vehicle may not pass this test. Return the vehicle to Original Equipment Manufacturer (OEM) condition before following this pinpoint test.



NOTE: If the engine is operated at greater than 2,000 Revolutions Per Minute (RPM) momentarily, the generator self-excites. Make sure when the generator is disconnected the engine RPM stays below 2,000 Revolutions Per Minute (RPM). If it rises above 2,000 Revolutions Per Minute (RPM), turn the ignition to the OFF position and start the test over again.



NOTE: Inspect for any aftermarket accessories that have been added to the vehicle. Check the wiring for these accessories and be sure they have not been attached to the generator circuits and are positioned away from the generator wiring.

Possible Sources

- Generator
- In-vehicle entertainment system
- Wiring, terminals or connectors

Visual Inspection and Diagnostic Pre-checks

- Inspect the generator.
- Inspect the in-vehicle entertainment system.

DIAGNOSIS AND TESTING > CHARGING SYSTEM - 5.0L 32V TI-VCT > PINPOINT TESTS (5.0L) > PINPOINT TEST D : RADIO INTERFERENCE > PINPOINT TEST D : RADIO INTERFERENCE

D1 VERIFY THE GENERATOR IS THE SOURCE OF THE AUDIO SYSTEM INTERFERENCE

Start the engine.

Allow the engine to idle.

Tune the audio system to a station where interference is present.