

K4M

II - FINAL OPERATION

- ☐ Remove the engine support tool (**Mot. 1453**).
- ☐ Refit the engine cover.