

EXHAUST

Silencer: Removal - Refitting

19B

EQUIPMENT LEVEL EAG

- the **exhaust sleeve (25 N.m)** whilst supporting the exhaust pipe.

II - FINAL OPERATION

☐ Check:

- that all the exhaust pipe heat shields are in place and properly attached,
- that there is no contact with the underbody,
- that there are no leaks.