

A 16 character code called C2I (Individual Injector Corrector) is marked on the injectors. This code, specific to each injector, takes into account any manufacturing variations and specifies the flow injected by each injector.

The code of the new injector must be programmed into the computer when injector is replaced.

The code of the four injectors must be programmed into the computer when the computer is replaced.

There are two possibilities:

- If it is possible to communicate with the computer:
 - Upload the data from the computer into the diagnostic tool,
 - change the computer,
 - download the data from the diagnostic tool to the computer.
 - Using the diagnostic tool, ensure that the computer has not detected faults relating to the injector codes and check that the instrument panel warning light is off.
- If it is not possible to communicate with the computer:
 - Change the computer,
 - read the data on the injectors,
 - store the data in the computer using the diagnostic tool.
 - Using the diagnostic tool, ensure that the computer has not detected faults relating to the injector codes and check that the instrument panel warning light is off.