



Repair-30x03x01x02-01x37-1-38-1.xml



XSL version : 3.02 du 22/07/11

mcx30.com


CLUTCH PEDAL SPRING: REMOVAL - REFITTING

Equipment required

pedal press

REMOVAL

1. REMOVAL OPERATION



113095