




Remove the sunroof operating mechanism (this operation requires two people) using the specific supports:

- Support: PARV 202,

- set of arch supports: APARV 200 ESP.



Repair-50x04x01x06-02x21-1-1-1.xml




DIAGNOSTIC SOCKET: LIST AND LOCATION OF COMPONENTS

Special tooling required

Set of trim removal levers.

Car. 1363

1. LOCATION



156525

Unclip the diagnostic socket cover(1) using the toolSet of trim removal levers.(Car. 1363) .