

Marks	Designations	Informations
1	Right-hand suspended engine mounting	(see Right-hand suspended engine mounting: Removal - Refitting) (Mot. 1453)
2	Engine - gearbox assembly	(see Engine - gearbox assembly: Removal - Refitting)
3	Lower engine tie-bar bolt on the subframe	
4	Lower engine tie-bar	(see Engine - gearbox assembly: Removal - Refitting)
5	Front axle subframe	(see Front axle subframe: Removal - Refitting)
6	Braket lower engine tie-bar rod	(see Engine - gearbox assembly: Removal - Refitting)
7	Braket axis left-hand	(see Left-hand suspended engine mounting: Removal - Refitting) (Mot. 1453)
8	Bracket-gearbox	(see Left-hand suspended engine mounting: Removal - Refitting) (Mot. 1453)
9	Bracket-mounting left-hand	(see Left-hand suspended engine mounting: Removal - Refitting) (Mot. 1453)
10	Mounting-élastic left-hand	(see Left-hand suspended engine mounting: Removal - Refitting) (Mot. 1453)



Repair-10x04x01x04-02x50-1-8-1.xml



mcx30.com




Illustration key: Description .

For fastenings with no specified tightening torque values, refer to the Table of Standard Torques [Tightening torques: General information](#).