




Repair-30x04x06x14-02x51-1-25-1.xml



XSL version : 3.02 du 22/07/11

RADIO: LIST AND LOCATION OF COMPONENTS



Note, one or more warnings are present in this procedure



Equipment required

Diagnostic tool

1. LIST OF COMPONENTS

1- THE RADIO SYSTEM COMPRISES:

- a radio aerial
- front speakers [Front side opening element assembly on the passenger compartment side: Exploded view](#)
- rear speakers [Rear side opening element assembly on the passenger compartment side: Exploded view](#)
- tweeters in the dashboard [Dashboard assembly: Exploded view](#)
- a radio control satellite
- a radio
- an offset multimedia socket
- an "hands-free" microphone

2. LOCATION OF COMPONENTS



CAUTION

To prevent damaging the navigation system, wait 1 minute after switching off the + after ignition feed.

CAUTION



To ensure correct operation:



do not pinch the aerial cable,



do not bend the aerial cable,





do not force the aerial cable when refitting.



1- AERIAL

mcx30.com





125120

2- RADIO CONTROL SATELLITE