

 In the event of a fault, replace the water inlet housing([see 19A, Cooling, Water chamber: Removal - Refitting](#))

 Apply the After repair procedure using the Diagnostic tool [Diagnostic tool : Use](#) :

-Computer concerned by the After repair procedure:



"Injection computer" ,

-Component controlled by this computer concerned by the After repair procedure:



"Thermostatic controlled component" .



Repair-10x06x03-01x37-1-71-1.xml



XSL version : 3.02 du 22/07/11


mcx30.com

THERMOSTAT:REMOVAL-REFITTING

Equipment required

Diagnostic tool

Locations and specifications (tightening torques, parts always to be replaced, etc.)([see 19A, Cooling, Coolant circuit assembly: Exploded view](#)) .



154193