

Disadvantages:



causes a large quantity of metal filings,



it is forbidden to drill vertically into the part.



Operator protection:



obligatory eye protection,



obligatory hand protection.



Protection in the work area:



protection of interior fittings.



Repair-00x04x03x14-01x79-1-1-1.xml

