


REAR BUMPER ASSEMBLY: EXPLODED VIEW



[Illustration key: Description](#) .

For fastenings with no specified tightening torque values, refer to the Table of Standard Torques [Tightening torques: General information](#) .

Marks	Designations	Informations
1	Rear bumper wiring	
2	Sensor helps parking lot	Proximity radar: Removal - Refitting@80,03,03,09-01,37-1
3	Radio aerial detection swipes	
4	Front bumper mounting	
5	Flap	
6	Reflector	
7	Rear bumper absorber	
8	Rear bumper	Material : P/E ,(Rear bumper: Removal - Refitting@50,05,04-01,37-1),(Polypropylene / polyethylene bodywork component: Preparation and paint range@40,01,45,07-02,65-1),(Plastic material bodywork component: Repair 40,01,45,10-01,22-1)
9	Rear bumper trim	Material : P/E UV

XSL version : 3.02 du 22/07/11

Repair-50x05x03-02x50-1-6-1.xml