

Module	DTC	Description	Action <i>New: hover over Pinpoint Test links to show title</i>
SCCM	B135C:13	Heater Element: Circuit Open	GO to Pinpoint Test O
SCCM	U0140:00	Lost Communication With Body Control Module: No Sub Type Information	GO to Pinpoint Test P
SCCM	U0140:00	SCCM: Lost Communication With Body Control Module: No Sub Type Information	GO to Pinpoint Test R
SCCM	U0146:00	SCCM: Lost Communication With Gateway "A": No Sub Type Information	GO to Pinpoint Test R
SCCM	U0146:87	SCCM: Lost Communication With Gateway "A": No Sub Type Information	GO to Pinpoint Test R
SCCM	U0155:00	SCCM: Lost Communication With Instrument Panel Cluster Module: No Sub Type Information	GO to Pinpoint Test R
SCCM	U023A:00	SCCM: Lost Communication With Image Processing Module "A": No Sub Type Information	GO to Pinpoint Test R
SCCM	U0241:00	SCCM: Lost Communication With Headlamp Control Module: No Sub Type Information	GO to Pinpoint Test R
SCCM	U210A:11	Temperature Sensor: Circuit Short To Ground	GO to Pinpoint Test O
SCCM	U210A:13	Temperature Sensor: Circuit Open	GO to Pinpoint Test O
SCCM	U3003:A2	Battery Voltage: System Voltage Low	GO to Pinpoint Test M
SCCM	U3003:A3	Battery Voltage: System Voltage High	GO to Pinpoint Test N

Symptom Charts

Symptom Chart: Ignition Switch - Conventional

Diagnostics in this manual assume a certain skill level and knowledge of Ford-specific diagnostic practices.
REFER to: Diagnostic Methods (100-00 General Information, Description and Operation).

Symptom Chart

Condition	Possible Causes	Actions
No power in all ignition switch positions	Refer to Pinpoint Test	GO to Pinpoint Test A
No power in ACC	Refer to Pinpoint Test	GO to Pinpoint Test B
No power in ON	Refer to Pinpoint Test	GO to Pinpoint Test C