

**DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM >  
PINPOINT TESTS > PINPOINT TEST AR : U0253:00**

**Normal Operation and Fault Conditions**

REFER to: Information and Entertainment System - System Operation and Component Description . See Network Message Chart.

**DTC Fault Trigger Conditions**

| DTC      | Description                                                                          | Fault Trigger Conditions                                                                                                                     |
|----------|--------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| U0253:00 | Lost Communication With Accessory Protocol Interface Module: No Sub Type Information | Set by the ACM, audio DSP module, and FCIM when network messages are missing from the APIM for more than 5 seconds with the ignition in RUN. |

**Possible Source**

- APIM

**DIAGNOSIS AND TESTING > INFORMATION AND ENTERTAINMENT SYSTEM >  
PINPOINT TESTS > PINPOINT TEST AR : U0253:00 > PINPOINT TEST AR : U0253:00**

AR1 VERIFY THE CUSTOMER'S CONCERN

Ignition ON.

Verify there is an observable symptom present.

**Is an observable symptom present?**

|            |           |
|------------|-----------|
| <b>Yes</b> | GO to AR2 |
|------------|-----------|

|           |                                                                                                                                           |
|-----------|-------------------------------------------------------------------------------------------------------------------------------------------|
| <b>No</b> | The system is operating correctly at this time. The DTC may have been set due to high network traffic or an intermittent fault condition. |
|-----------|-------------------------------------------------------------------------------------------------------------------------------------------|

AR2 RECHECK FOR DTC (DIAGNOSTIC TROUBLE CODE) U0253:00

Ignition ON.

Using a diagnostic scan tool, clear all Continuous Memory Diagnostic Trouble Codes (CMDTCs).

Ignition OFF.