

Front Turn Signal Lamp Bulb

Base Part Number: Base Part Number: 13466


Removal

Vehicles with headlamps


1. Bulbs are not serviceable on LED headlamps. Replace the headlamp assembly.

Vehicles equipped with halogen headlamps

2. Remove the pushpins and screws, Position the fender liner aside.



3. Remove the bulb holder and remove the turn signal bulb.



E190808



Installation

1. To install, reverse the removal procedure.

Copyright © 2018 Ford Motor Company