

Description and Operation

Overview

The vehicle has 2 module communication networks connected to the [DLC \(data link connector\)](#), located under the instrument panel. The communication networks are:

- [HS-CAN1 \(high-speed controller area network 1\)](#)
- [HS-CAN2 \(high-speed controller area network 2\)](#)

The vehicle has 2 module communication networks that communicate on the network, but do not communicate directly with the diagnostic scan tool. The [GWM \(gateway module A\)](#) translates the messages on these 2 networks, and transfers the signals to the [HS-CAN2](#) to communicate with the diagnostic scan tool. The communication networks are:

- [HS-CAN3 \(high-speed controller area network 3\)/ I-CAN \(controller area network\)](#)
- [MS-CAN \(medium speed-controller area network\)](#)

mcx30.com