

Install the automatic transmission. Refer to: Transmission - 2.3L EcoBoost (231kW/314PS) .

3.

After completing the repairs, perform the Misfire Monitor Neutral Profile Correction procedure using a diagnostic scan tool.

REMOVAL AND INSTALLATION > FLYWHEEL

Special Tool(s) / General Equipment



303-103 (T74P-6375-A) Holding Tool, Flywheel T74P-77000-A
TKIT-2009TC-F

REMOVAL AND INSTALLATION > FLYWHEEL > REMOVAL

1.

With the vehicle in NEUTRAL, position it on a hoist. Refer to: Jacking and Lifting - Overview .

2.

Remove the clutch. Refer to: Clutch Disc and Pressure Plate - 2.3L EcoBoost (201kW/273PS) .

3.

Install Special Service Tool: 303-103 (T74P-6375-A) Holding Tool, Flywheel.



NOTE: Do not reuse the flywheel bolts.

Remove the bolts and the flywheel.

Discard the bolts.