

|                |   |                                                                      |
|----------------|---|----------------------------------------------------------------------|
| All Other DTCs | - | Refer to ENGINE CONTROLS - SYMPTOM CHARTS (EXCEPT DIESEL & HYBRID) . |
|----------------|---|----------------------------------------------------------------------|

## DIAGNOSIS AND TESTING > ELECTRONIC ENGINE CONTROLS > PINPOINT TESTS > PINPOINT TEST A : U0121

### DTC Fault Trigger Condition-PCM

| DTC   | Description                                                         | Fault Trigger Conditions                                                                                                              |
|-------|---------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|
| U0121 | Lost Communication With Anti-Lock Brake System (ABS) Control Module | The PCM sets this DTC if data messages received from the ABS module over the High Speed Controller Area Network (HS-CAN) are missing. |

### Normal Operation and Fault Conditions

REFER to: MODULE COMMUNICATIONS NETWORK .

### Possible Sources

- ABS module
- BCM
- PCM

## DIAGNOSIS AND TESTING > ELECTRONIC ENGINE CONTROLS > PINPOINT TESTS > PINPOINT TEST A : U0121 > PINPOINT TEST A : U0121

### A1 VERIFY THE CUSTOMER CONCERN

Ignition ON.

Verify there is an observable symptom present.

### Is an observable symptom present?

|     |                                                                                                                                          |
|-----|------------------------------------------------------------------------------------------------------------------------------------------|
| Yes | GO to A2                                                                                                                                 |
| No  | The system is operating normally at this time. The DTC may have been set due to high network traffic or an intermittent fault condition. |

### A2 CHECK THE COMMUNICATION NETWORK