

Diagnosis and Testing

General Equipment

[Ford diagnostic equipment](#)

Refer to Wiring Diagram Section 085-1 for schematic and connector information.

Inspection and Verification

1. Verify the customer concern.
2. Visually inspect for obvious signs of electrical damage.

VISUAL INSPECTION

Electrical
• Fuse(s) • Relay(s) • Wiring harness • Electrical connector(s) • Switch • Lamp(s)

3. If an obvious cause for an observed or reported concern is found, correct the cause (if possible) before proceeding to the next step.
4. If the cause is not visually evident, verify the symptom and refer to the [Ford diagnostic equipment](#) to diagnose the system.