

Removal and Installation**Special Tool(s) / General Equipment**

	415-001 Remover, Audio Unit
 E84511	501-125 Remover, Grab Handle Cover
Hot Glue Gun	
Interior Trim Remover	

Removal

NOTE: Removal steps in this procedure may contain installation details.


1. On both sides.

Refer to: [A-Pillar Trim Panel](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

2. Refer to: [Rear Headliner](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

Vehicles with tachograph

3. Remove *Special Service Tool*: [415-001](#).



E141529


4.



E146563

Vehicles without tachograph


5. Remove Special Service Tool: [501-125](#).



E141559


All vehicles

6.




E141540

7. On both sides.



E71813


8. On both sides.



E141536


Vehicles without front view camera

9.



E141281


10.



E141535


Vehicles with front view camera

11.



E140621

12. Use the General Equipment: [Interior Trim Remover](#)



E140622


13.




E141534

All vehicles


14. On both sides.




15.



16.  NOTICE: Take extra care not to crease the headliner.




17.  NOTICE: Take extra care not to crease the headliner.




NOTE: The following steps are only necessary when installing a new component.

18.  NOTICE: Replace interior lamp bulbs only from the back side of the lamp, removing the glass causes malfunction.




E92068

19.




E141544

20.




E133571


21.




22.



23. On both sides.



24. **NOTE:** Note the position of the components before removal.
Use the General Equipment: [Hot Glue Gun](#)



E141549

Installation

1. **NOTE:** Make sure that the components are installed to the position noted before removal.
To install, reverse the removal procedure.