



Carry out a function test on all functions.



Repair-40x10x02x08-01x37-1-4-1.xml



XSL version : 3.02 du 22/07/11

mcx30.com

FRONT SIDE OPENING ELEMENT TRIM: REMOVAL - REFITTING


Special tooling required

Set of trim removal levers.

Car. 1363


REMOVAL

1. REMOVAL OPERATION



■ Unclip the blanking covers(1) .

■ Remove the screws(1) and (2) .



Remove:



the front side door interior handle screw(3) ,



the front side door opening handle using the toolSet of trim removal levers.(Car. 1363) .



Unclip the electric window switch plate using the toolSet of trim removal levers.(Car. 1363) from the front side door trim(4) .



Disconnect the front electric window switch connectors.

