

Remove the front side door trim using a pair of unclipping pliers.

REFITTING

1. REFITTING PREPARATION OPERATION



Check the condition of the clips and replace them if necessary.

2. REFITTING OPERATION



Proceed in the reverse order to removal.



Carry out a function test.




Repair-70x03x02x27-01x37-1-4-1.xml



XSL version : 3.02 du 22/07/11

FRONT SIDE WINDOW MECHANISM ASSEMBLY: EXPLODED VIEW



159898

[Illustration key: Description](#).

For fastenings with no specified tightening torque values, refer to the Table of Standard Torques: [Tightening torques: General information](#).