




INSTRUMENT PANEL AND CONSOLE (G2344393)





SPECIFICATIONS

Torque specification

COMPONENT TORQUE LOCATION



COMPONENT TORQUE LOCATION



	DESCRIPTION	NM	LB-IN	LB-IN
1	Floor console cup holder retaining screws	1.5	13	80

	DESCRIPTION	NM	LB-IN	LB-IN
2	Floor console rear stowage compartment screws	1.7	15	80
3	Floor console stowage compartment lid screws	8	71	80
4	Glovebox bolts	5	44	80
5	Instrument panel lower trim bolts	2.5	22	80
6	Instrument panel lower trim screw	1.7	15	80
7	instrument panel upper trim panel bolts	12	106	44
8	instrument panel cross-car beam bolts	25	221	44

cmjjaGFyZG1vbnRvbjsyMDIwLTA5LTE4VDEzOjAzOjAyLjg5SMVo7OTIuNDAuMTg5LjUzOw==

mcx30.com