


SECTION 303-01A: Engine — 3.5L GTDI
IN-VEHICLE REPAIR

2014 F-150 Workshop Manual
Procedure revision date: 10/25/2013

Crankshaft Pulley and Crankshaft Front Seal — Exploded View



Item	Part Number	Description
1	W701512	Crankshaft pulley bolt
2	N806165	Washer
3	6312	Crankshaft pulley
4	6700	Crankshaft front seal

1. Refer to the procedures and/or exploded views in this section for any Warnings, Notices, Notes, Materials, Specifications, and Special Tools. Items in the exploded views may not be listed in order of removal.

mcx30.com