



Type

S/Section

Electric vehicle

XXX X

24A

24A INSULATION FAULT FINDING ON ELECTRIC VEHICLES

- Engine: XXX
- Gearbox: XXX

Basic manual: any Technical Note

This Technical Note concerns the operations to be performed when searching for an electrical insulation fault on a power circuit of an electric vehicle or hybrid electric combustion engine vehicle with a megohmmeter or insulation tester.

"The repair procedures given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The procedures may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All rights reserved by Renault s.a.s.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault s.a.s.